

BILL LUKE

Family Owned and Operated Since 1927

In 1873, a teenager with an adventuresome spirit rode into a remote western town populated by about 1,000 hardy souls, liked what he saw, and decided to put down his roots in the desert. His name was Frank Luke and the town was Phoenix. In the years that followed, Frank married, raised nine children, prospered in business and spent the last 20 years of his life in public service. At the time of his death, in 1939, he was State Tax Commissioner.

Frank Luke jr. was the fifth child of Ottilia and Frank Luke. He only lived for 21 years but his name and deeds will live forever in American military history. Second only to Captain Eddie Rickenbacker, as the leading ace of World War I, Luke was credited with 18 kills in nine months of combat. Rickenbacker was quoted as saying: Had he (Luke) lived, he would have put me out of business as the Army's leading ace. Lieutenant Frank Luke, Jr. was posthumously awarded the Congressional Medal of Honor, had a statue erected in his memory in the mall of the State Capitol and was further honored when Luke Air Force Base was named after him.

William "Bill" Luke was the youngest of Ottilia and Frank Luke, Sr.'s nine children. He was always fascinated by machines and in 1927, at the age of 18, jumped at the opportunity to get in on the ground floor of a young, growing industry. He was to become the founder of Bill Luke Chrysler-Plymouth and continued as head of the automobile dealership until his passing in 1988. During his years as an automobile dealer, Bill Luke found time to pursue interests in farming, cattle ranching, and was a breeder of thoroughbred horses. At one time he owned a stable of 70 race horses and won the Arizona Breeders Award many times.

Dorothy and Bill Luke had five children. The youngest was named Donald "Don" Luke, and, like his father displayed an early interest in machines. He began working in the family business at the age of 13, progressed up the ladder to General Manager and then to President and CEO of the Bill Luke Dealerships. Don has three sons Ryan, Chris, and Eric... bringing the total number of direct descendants of the Arizona pioneers, Ottilia and Frank Luke, Sr. to well over 100.



BILL LUKE TEMPE



STELVIO QUADRIFOGLIO
MAINTENANCE GUIDE

2018 STELVIO 2.9

	10k	20k	30k	40k
Check battery charge status with proper instrument	X	X	X	X
Check tire condition/wear and adjust pressure				
check the tire repair kit and recharge condition	X	X	X	X
Check operation of lighting system (headlamps, directional indicators, hazard warning lights, deck lid, passenger compartment, glove compartment instrument panel warning lights, etc.)	X	X	X	X
check and, if necessary, top up fluid levels.	X	X	X	X
Check engine control system via diagnostic tool.	X	X	X	X
Visually inspect conditions of; exterior bodywork, underbody protection, pipe hoses		X		X
Check position/wear of front windshield wiper blade	X		X	
Check operation of windshield washer spray system	X		X	
Check cleanliness of hood and luggage compartment locks, and lubrication of linkage		X		X
Visually inspect condition and wear of front/rear brake disc brake pads and operation of wear indicator				
Brake disc wear status check with dianostic tool				
visually inspect the brake disc surface and edge	X	X	X	X
Visually inspect condition of drive belts	X	X	X	
Change oil and replace oil filter	The actual interval per			
replace accessory drive belt	Non dusty maximum			
Replace air cleaner cartridge.		X		X
Change the brake fluid	Brake fluid			
Replace the passenger compartment cleaner	0	X	0	X
Spark plug replacement. Mileage based only.			X	

(x) Mandatory operation \$371.00 \$821.00 \$820.00 \$1,380.00

(0) Recommended operation * ** * ***

* Includes oil change

** Includes oil change brake fluid

*** includes oil change, brake fluid, belt

**** Includes oil change belt

	50k	60k	70k	80k	90k	100k
	X	X	X	X	X	X
	X	X	X	X	X	X
	X	X	X	X	X	X
	X	X	X	X	X	X
		X		X		X
	X		X		X	
	X		X		X	
		X		X		X
	X	X	X	X	X	X
	X	X	X		X	X
warning light. Never exceed 1 year/10,000 miles						
mileage 36,000/ 4 years . Heavy usage 18,000 miles 2 year						
	X		X			X
replacement has to be done every two years						
0	X	0	X	0		X
	X				X	
\$371.00	\$ 1,270.00	\$930.00	\$821.00	\$820.00	\$876.00	
*	**	****	**	*	**	

STELVIO

